



| Pressure Vs Torque Conversion Chart | | | | |
|--|---------------|--|-----------------|---------------|
| <i>Titan T10 Square Drive Tool</i> | | | | |
| Pressure | <i>Torque</i> | | Pressure | <i>Torque</i> |
| Psi | <i>Ft-Lb</i> | | Bar | <i>Kgm Nm</i> |
| 1500 | 1662 | | 103 | 229 2254 |
| 1600 | 1773 | | 110 | 245 2404 |
| 1800 | 1994 | | 124 | 275 2704 |
| 2000 | 2236 | | 138 | 309 3032 |
| 2200 | 2460 | | 152 | 339 3335 |
| 2400 | 2683 | | 166 | 370 3638 |
| 2600 | 2907 | | 179 | 401 3942 |
| 2800 | 3130 | | 193 | 432 4245 |
| 3000 | 3365 | | 207 | 464 4563 |
| 3200 | 3589 | | 221 | 495 4867 |
| 3400 | 3814 | | 235 | 526 5171 |
| 3600 | 4038 | | 248 | 557 5476 |
| 3800 | 4262 | | 262 | 588 5780 |
| 4000 | 4456 | | 276 | 615 6042 |
| 4200 | 4679 | | 290 | 646 6344 |
| 4400 | 4902 | | 304 | 676 6647 |
| 4600 | 5124 | | 317 | 707 6949 |
| 4800 | 5347 | | 331 | 738 7251 |
| 5000 | 5588 | | 345 | 771 7577 |
| 5200 | 5812 | | 359 | 802 7880 |
| 5400 | 6035 | | 373 | 833 8184 |
| 5600 | 6259 | | 386 | 864 8487 |
| 5800 | 6482 | | 400 | 895 8790 |
| 6000 | 6717 | | 414 | 927 9108 |
| 6200 | 6941 | | 428 | 958 9412 |
| 6400 | 7165 | | 442 | 989 9715 |
| 6600 | 7389 | | 455 | 1020 10019 |
| 6800 | 7613 | | 469 | 1051 10323 |
| 7000 | 7746 | | 483 | 1069 10504 |
| 7200 | 7967 | | 497 | 1099 10804 |
| 7400 | 8189 | | 511 | 1130 11104 |
| 7600 | 8410 | | 524 | 1161 11404 |
| 7800 | 8631 | | 538 | 1191 11704 |
| 8000 | 8867 | | 552 | 1224 12024 |
| 8200 | 9089 | | 566 | 1254 12324 |
| 8400 | 9310 | | 580 | 1285 12625 |
| 8600 | 9532 | | 593 | 1315 12925 |
| 8800 | 9754 | | 607 | 1346 13226 |
| 9000 | 10075 | | 621 | 1390 13662 |
| 9200 | 10299 | | 635 | 1421 13965 |
| 9400 | 10523 | | 649 | 1452 14269 |
| 9600 | 10747 | | 662 | 1483 14572 |
| 9800 | 10971 | | 676 | 1514 14876 |
| 10000 | 11067 | | 690 | 1527 15007 |