



| Pressure Vs Torque Conversion Chart | | | | | |
|--|---------------|--|-----------------|---------------|-----------|
| <i>Titan LP4 Low Profile</i> | | | | | |
| Pressure | <i>Torque</i> | | Pressure | <i>Torque</i> | |
| Psi | <i>Ft-Lb</i> | | Bar | <i>Kgm</i> | <i>Nm</i> |
| 1500 | 568 | | 103 | 78 | 770 |
| 1600 | 606 | | 110 | 84 | 822 |
| 1800 | 682 | | 124 | 94 | 924 |
| 2000 | 758 | | 138 | 105 | 1028 |
| 2200 | 834 | | 152 | 115 | 1131 |
| 2400 | 910 | | 166 | 126 | 1233 |
| 2600 | 985 | | 179 | 136 | 1336 |
| 2800 | 1061 | | 193 | 146 | 1439 |
| 3000 | 1136 | | 207 | 157 | 1540 |
| 3200 | 1212 | | 221 | 167 | 1643 |
| 3400 | 1287 | | 235 | 178 | 1746 |
| 3600 | 1363 | | 248 | 188 | 1848 |
| 3800 | 1439 | | 262 | 199 | 1951 |
| 4000 | 1515 | | 276 | 209 | 2054 |
| 4200 | 1591 | | 290 | 220 | 2157 |
| 4400 | 1667 | | 304 | 230 | 2260 |
| 4600 | 1742 | | 317 | 240 | 2362 |
| 4800 | 1818 | | 331 | 251 | 2465 |
| 5000 | 1894 | | 345 | 261 | 2568 |
| 5200 | 1970 | | 359 | 272 | 2671 |
| 5400 | 2046 | | 373 | 282 | 2774 |
| 5600 | 2121 | | 386 | 293 | 2876 |
| 5800 | 2197 | | 400 | 303 | 2979 |
| 6000 | 2273 | | 414 | 314 | 3082 |
| 6200 | 2349 | | 428 | 324 | 3185 |
| 6400 | 2425 | | 442 | 335 | 3288 |
| 6600 | 2500 | | 455 | 345 | 3390 |
| 6800 | 2576 | | 469 | 355 | 3493 |
| 7000 | 2652 | | 483 | 366 | 3596 |
| 7200 | 2728 | | 497 | 376 | 3699 |
| 7400 | 2804 | | 511 | 387 | 3802 |
| 7600 | 2879 | | 524 | 397 | 3904 |
| 7800 | 2955 | | 538 | 408 | 4007 |
| 8000 | 3030 | | 552 | 418 | 4109 |
| 8200 | 3106 | | 566 | 429 | 4211 |
| 8400 | 3182 | | 580 | 439 | 4314 |
| 8600 | 3257 | | 593 | 450 | 4417 |
| 8800 | 3333 | | 607 | 460 | 4520 |
| 9000 | 3409 | | 621 | 470 | 4623 |
| 9200 | 3485 | | 635 | 481 | 4725 |
| 9400 | 3561 | | 649 | 491 | 4828 |
| 9600 | 3636 | | 662 | 502 | 4931 |
| 9800 | 3712 | | 676 | 512 | 5034 |
| 10000 | 3788 | | 690 | 523 | 5137 |