



Pressure Vs Torque Conversion Chart				
<i>Titan T25 Square Drive Tool</i>				
Pressure	<i>Torque</i>		Pressure	<i>Torque</i>
Psi	<i>Ft-Lb</i>		Bar	<i>Kgm Nm</i>
1500	3726		103	514 5052
1600	3974		110	548 5389
1800	4471		124	617 6063
2000	5106		138	705 6924
2200	5617		152	775 7616
2400	6127		166	846 8308
2600	6638		179	916 9001
2800	7148		193	986 9693
3000	7704		207	1063 10447
3200	8218		221	1134 11143
3400	8731		235	1205 11840
3600	9245		248	1276 12536
3800	9758		262	1347 13232
4000	10288		276	1420 13951
4200	10802		290	1491 14648
4400	11317		304	1562 15346
4600	11831		317	1633 16043
4800	12346		331	1704 16741
5000	12894		345	1779 17484
5200	13410		359	1851 18184
5400	13926		373	1922 18883
5600	14441		386	1993 19582
5800	14957		400	2064 20282
6000	15348		414	2118 20812
6200	15860		428	2189 21506
6400	16371		442	2259 22199
6600	16883		455	2330 22893
6800	17394		469	2400 23587
7000	17778		483	2453 24107
7200	18286		497	2523 24796
7400	18794		511	2594 25485
7600	19302		524	2664 26173
7800	19810		538	2734 26862
8000	20146		552	2780 27318
8200	20650		566	2850 28001
8400	21153		580	2919 28684
8600	21657		593	2989 29367
8800	22161		607	3058 30050
9000	22510		621	3106 30524
9200	23010		635	3175 31202
9400	23510		649	3244 31880
9600	24011		662	3313 32558
9800	24511		676	3383 33237
10000	24749		690	3415 33560