



Pressure Vs Torque Conversion Chart					
<i>Titan T3 Square Drive Tool</i>					
Pressure	<i>Torque</i>		Pressure	<i>Torque</i>	
Psi	<i>Ft-Lb</i>		Bar	<i>Kgm</i>	<i>Nm</i>
1500	468		103	65	635
1600	499		110	69	677
1800	562		124	78	762
2000	644		138	89	873
2200	708		152	98	961
2400	773		166	107	1048
2600	837		179	116	1135
2800	902		193	124	1223
3000	961		207	133	1303
3200	1025		221	141	1390
3400	1089		235	150	1477
3600	1153		248	159	1564
3800	1217		262	168	1651
4000	1278		276	176	1733
4200	1342		290	185	1820
4400	1406		304	194	1906
4600	1470		317	203	1993
4800	1534		331	212	2080
5000	1592		345	220	2159
5200	1656		359	228	2245
5400	1719		373	237	2331
5600	1783		386	246	2418
5800	1847		400	255	2504
6000	1896		414	262	2571
6200	1959		428	270	2657
6400	2022		442	279	2742
6600	2086		455	288	2828
6800	2149		469	297	2914
7000	2190		483	302	2970
7200	2253		497	311	3054
7400	2315		511	319	3139
7600	2378		524	328	3224
7800	2440		538	337	3309
8000	2497		552	345	3386
8200	2559		566	353	3471
8400	2622		580	362	3555
8600	2684		593	370	3640
8800	2747		607	379	3725
9000	2810		621	388	3810
9200	2872		635	396	3895
9400	2935		649	405	3980
9600	2997		662	414	4064
9800	3060		676	422	4149
10000	3124		690	431	4236